



Casting thickness should not exceed 1/8 thick except for structural purposes.

Crankcase - Make a second one without crankshaft bearing supports for the opposite side of engine.

Crankcase	Left Side	Date : 18-Jan-2010	Project: BECO 2.0
		Drawn by: Glen Bond	Drawing: Crankcase
All dimensions are inches unless specified.			